











75

Roebuck - South East Lake Property Conditions

-  Roebuck - South East Lake Community
-  Sound Occupied
-  Sound Unoccupied
-  Deteriorated Occupied
-  Deteriorated unoccupied
-  Dilapidated Occupied
-  Dilapidated Unoccupied
-  Vacant Maintained
-  Vacant Overgrown
-  Vacant Natural

